






Fig. 1



2/11

Fig. 2.




10/510050

3/11

saliva pH value measured by Twin pH




F
gq
3



10/510050

4/11

Fig. 4



10 / 510050

5/11





Fig. 6



10/510050

7/11

F
go.

40

⇒ chart of Ms. Yashiro Akiko

e-mail : Y_akiyo@...

{ Jan. 1, 2000 inspection pH 6.5 pH ... Δ
Aug. 16, 2000 inspection pH 5.3 pH ... x

Sept. 1~28, 2000 treatment

Oct. 3, 2001 inspection

Nov. 27, 2001 inspection

Jul. 22, 2002 inspection pH 5.0 pH ... x

42 {
※ caries level 4 → 43a


43 {
※ There is a decayed tooth. Urgent treatment is needed. → 43b
※ Your mouth condition is ... You make it a point to ...
To make your mouth condition better, you can use one on this list. 43d

(S)

43d

16a

40 {
dentist list



41

10/510050

8/11

F
gg.
8

registered dentist list

51

52

○ ○ dental surgery ○○-○ Minami-ku Kyoto-shi Kyoto

Δ ○ clinic

Δ Δ dental surgery

50

53

reserved
date

reserved
date

01510050

9/11

F
gq.

We recommend for making your mouth condition better.

64

61

63


9

60

N E W ○○ liquid ... oxidized mouth

No. 1 ○△ coat ... face of tooth

ΔΔ clean ... of mouth condition





10/510050

10/11

qq. 10

individual chart	name :	Yashiro Akiko	the fourties	housewife
71	inspection date	2000/ 1/ 1	pH5.5	pH buffer capacity
72		2000/ 8/16	pH5.3	detail
72		2000/10/ 3	pH6.8	detail
72		2001/11/27	pH6.5	detail
72		2002/ 7/22	pH5.0	detail
73	→ treatment	treatment of the Oth tooth on the upper jaw.	OO dental surgery	detail
74	guideline	advice about treatment : She is allergic to ... pH value is down, pH buffer capacity ... such a patient is ..., it needs ...		↑ 16b

Fig. 11



(B)

(A)

